



**1885554**

## **O-Sullivan Bench**

### **Parts List**

A.	Top Assembly	1 pc
B.	Stretcher	1 pc
C.	Spindles	4 pcs
D.	Feet	4 pcs
E.	Finial	1 pc

\* Please make sure that you have all the parts indicated above before you begin assembly of this item.

\* This item should be assembled on a soft surface to prevent scratching the finish during assembly.

\* This item may require periodic tightening.

### **Assembly Instructions**

1. **Attach Spindles (C) to Top Assembly (A)** Put the Top Assembly (A) upside down on a soft surface. Align the exposed threads of Spindles (C) with the pre-threaded holes in the blocks of Top Assembly (A). Tighten by turning in a clockwise direction. See Illustration.
2. **Attach Finial (E)** Align the threads of Finial (E) with the pre-threaded hole in the middle of Stretcher (B). Tighten by turning in a clockwise direction. See Illustration.
3. **Attach Stretcher (B) & Feet (D)** Align the pre-drilled holes in the Stretcher (B) with the pre-threaded holes in the Spindles (C). Make sure finial of Stretcher (B) is downward. Insert the exposed threads on the Feet (D) through the pre-drilled holes in the Stretcher (B) and into the pre-threaded holes of the Spindles (C). Tighten by turning in a clockwise direction. See Illustration.

